 <p>PHONE: 263 4 585018 263 4 585073/88 FAX: 263 4 585100 E-mail: ais@caaz.co.zw Website: www.caaz.co.zw</p>	<p>CIVIL AVIATION AUTHORITY OF ZIMBABWE</p> <p>AERONAUTICAL INFORMATION SERVICES P. BAG 7716 CAUSEWAY, HARARE</p>	<p>AIC</p> <p>B034/01</p> <p>23 APR 2001</p>
---	---	--

AERONAUTICAL INFORMATION CIRCULAR


AIC B39/94 is hereby replaced

COMPASS INTERFERENCE AUTHORITY

Instances continue to occur of aircraft becoming lost due to compass errors caused by the carriage of the following items in the cockpit:

- Transistor radios, Walkman, CD player, portable phones and headset,
- Torches, especially those with magnetic hold attachment,
- Metal bulldog clips,
- Cigarette cases and cigarette lighters,
- Metal computers,
- Certain types of microphones,
- Tool kits and any heavy ferrous objects
- Global Position Equipment (GPS).

Pilots should ensure that no equipment of this nature is placed near the compass, and passengers should be warned accordingly.



K Kaseke
Acting General Manager

This AIC is issued for information guidance and necessary action.